North America Emission Control Area Fuel Oil Non-Availability Report
ECA0100

1 2

##
##(Include Double Pound for comments, not form fields)
##Report Form ID Ship Operator Name

OOCLFMDFBS OOCL

3 4 5 6 7

Vessel Name Flag Country IMO ID Number Date of ECA First Notice Location of ECA First Notice

OOCL VANCOUVER Panama 9306990 5-Jul Halifax

Name of Ports after First Notice Name of Last Port before ECA Entry

Savannah; Norfolk; New York Cagliari

Name of Port with Fuel Oil Supply Disruption Name of Original Fuel Supplier with Disruption

NA NA

| 12 | 13 | 14 |
|------------------------------------|--------------------------|--------------------------|
| Number of Fuel Suppliers Contacted | Date of Entry in the ECA | Time of Entry in the ECA |
| NA | 03rd July 2013 | 1600 UTC |

15 16 17

Sulfur Content of Non-Compliant Fuel Oil Projected Hours on Main Propulsion Name of First POC

3.43% 41.5 hrs for completion of Change- Halifax over to LSFO

Compliance Fuel Oil Available at First POC? Plan to Bunker Compliant Fuel Oil at First POC?

YES YES

| 20 |) 21 | 22 |
|---|--------------------|-----------------------------------|
| Number of fuel suppliers contacted at First POC | Name of Second POC | Compliant Fuel Oil at Second POC? |
| NA . | NA | NA |

Plan to Bunker Compliance Fuel Oil at Second POC? Number of Fuel Suppliers Contacted at the Second POC?

NA NA

25 26 27

Date of Exit from ECA? Time of Exit from ECA? Has this vessel operated in the ECA in previous 12 months?

13th July 2013 0400 UTC

YES

Number of Separate Visits to the ECA Number of Ports visited in the ECA Previously submitted ECA0100 forms?

3 PORTS VISITED, EACH CALL, IN NA FOLLOWING ROTATION: HALIFAX, NEW YORK, SAVANNAH, NORFOLK, NEW YORK & HALIFAX

| 3 | L 32 | . 33 |
|-----------------------------|------------------------------------|--------------------------------------|
| Number of Submitted Reports | Designated Corporate Official Name | Designated Corporate Official E-mail |
| NA | NA | NA |

Designated Corporate Official Phone Number Description of Actions to Achieve Compliance

NΑ

In fact, we plan to arrange 500mt LSFO at Halifax, and it should reach next port NYC safely. However, the port rotation was changed suddenly. We tried the best to increase order qty to 650mt at Halifax, but failed; secondly, we tried to source LSFO at next port Savannah, but failed. Finally, we could only arrange LSFO replenishment on the 9-July at Norfolk.